



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

PRODUCT DISCONTINUANCE NOTICE# CQ-16-02

ISSUE DATE: August 26, 2016

LAST BUY DATE: August 26, 2017

LAST SHIP DATE: November 26, 2017

REASON FOR DISCONTINUANCE:

The sales activity has declined to a level that warrants the discontinuance of these products. Some of these devices may have an alternate standard device or a suggested functional replacement.

Attached is a list of affected parts with any potential drop in replacement parts or suggested functional replacement parts.

Customers should contact IDT within 90 days of receipt of this notification if they have any additional questions or concerns related to this Product Discontinuance Notice. You may contact your local IDT Sales office listed on our web site at www.IDT.com or the marketing contact listed below:

NET	clocks@idt.com
	Carl May
SPO	408-284-2718
	carl.may@idt.com
	Victor Abarca
MMT	408-284-6578
	victor.abarca@idt.com
	Paul Barton
MIP	408-284-8306
	paul.barton@idt.com
	Matt Jones
ACP	408-360-5622
	matt.jones@idt.com
	Trevor Hiatt
FCM	408-284-4530
	trevor.hiatt@idt.com

Final orders may be submitted at any time prior to the last buy date indicated above. All orders shall be subject to acceptance per IDT standard terms and conditions.



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
1337BDCGI	1337AGDCGI	None	Available now	MMT
1337BDCGI8	1337AGDCGI8	None	Available now	MMT
5P90011PGGI	None	None	N/A	MMT
5P90011PGGI8	None	None	N/A	MMT
80HCPS1848CBR-5	None	None	N/A	FCM
80HCPS1848CBR-58	None	None	N/A	FCM
80HVPS1616BR	None	80HCPS1616CBLG	Available now	FCM
80HVPS1616BR8	None	80HCPS1616CBLG8	Available now	FCM
80HVPS1616BRI	None	80HCPS1616CBLGI	Available now	FCM
80HVPS1616BRI8	None	80HCPS1616CBLGI8	Available now	FCM
80HVPS1616CBR	None	80HCPS1616CBLG	Available now	FCM
80HVPS1616CBR8	None	80HCPS1616CBLG8	Available now	FCM
80HVPS1616CBRI	None	80HCPS1616CBLGI	Available now	FCM
80HVPS1616CBRI8	None	80HCPS1616CBLGI8	Available now	FCM
80HVPS1616CBRI-L	None	None	N/A	FCM
80HVPS1616CBRI-L8	None	None	N/A	FCM
80HVPS1616RM8	None	80HCPS1616CHMG8	Available now	FCM
80HVPS1616RMI8	None	80HCPS1616CHMG8I8	Available now	FCM
80KSW0002RM	80KSW0002HMG	None	Available now	FCM
80KSW0002RM8	80KSW0002HMG	None	Available now	FCM
80KSW0002RMI	80KSW0002HMG1	None	Available now	FCM
80KSW0002RMI8	80KSW0002HMG1	None	Available now	FCM
80KSW0003AR	None	TSI574-10GCLV	Available now	FCM
80KSW0003ARI	None	TSI574-10GILV	Available now	FCM
80KSW0003RMI	None	TSI574-10GILV	Available now	FCM
80KSW0003RMI8	None	TSI574-10GILV	Available now	FCM
80KSW0004RMI	None	TSI578A-10GILV	Available now	FCM
80KSW0004RMI8	None	TSI578A-10GILV	Available now	FCM
80KSW0005BR	None	TSI578A-10GCLV	Available now	FCM
80KSW0005BR8	None	TSI578A-10GCLV	Available now	FCM
80KSW0005BRI	None	TSI578A-10GILV	Available now	FCM
80KSW0005BRI8	None	TSI578A-10GILV	Available now	FCM
8344BYILF	None	8344AYI-01LF	Available now	NET
8344BYILFT	None	8344AYI-01LFT	Available now	NET
83PN161AKILF	None	8N3PG10MBKI-161LF	Available now	NET
83PN161AKILFT	None	8N3PG10MBKI-161LFT	Available now	NET
841402DKILF	None	8T49N241-dddNLGI	Available now	NET
841402DKILFT	None	8T49N241-dddNLGI8	Available now	NET
843004AGLF	None	8T49N241-dddNLGI	Available now	NET
843004AGLFT	None	8T49N241-dddNLGI8	Available now	NET
8430S10AYILF	None	8430S10BYI-03LF	Available now	NET
8430S10AYILFT	None	8430S10BYI-03LFT	Available now	NET
843156AKILF	None	8T49N242-dddNLGI	Available now	NET
843156AKILFT	None	8T49N242-dddNLGI8	Available now	NET
843241BGLF	None	8T49N242-dddNLGI	Available now	NET
843241BGLFT	None	8T49N242-dddNLGI8	Available now	NET
843242AGLF	None	8T49N242-dddNLGI	Available now	NET
843242AGLFT	None	8T49N242-dddNLGI8	Available now	NET
843251AG-04LF	None	83PN156DKILF	Available now	SPO
843251AG-04LFT	None	83PN156DKILFT	Available now	SPO
843251AGI-04LF	None	83PN156DKILF	Available now	SPO
843251AGI-04LFT	None	83PN156DKILFT	Available now	SPO
844008BYI-15LF	None	844201BKI-45LF	Available now	NET
844008BYI-15LFT	None	844201BKI-45LFT	Available now	NET
8440258AKI-45LF	None	None	N/A	NET
8440258AKI-45LFT	None	None	N/A	NET
844252AG-04LF	None	8T49N242-dddNLGI	Available now	NET
844252AG-04LFT	None	8T49N242-dddNLGI8	Available now	NET
852S41AYLF	None	None	N/A	NET
852S41AYLFT	None	None	N/A	NET
87322BYILF	None	87321AMILF & 853S12AKILF	Available now	NET
87322BYILFT	None	87321AMILFT & 853S12AKILFT	Available now	NET
8752CYILF	None	8T49N286A-dddNLGI	Available now	NET
8752CYILFT	None	8T49N286A-dddNLGI8	Available now	NET
8752CYLF	None	8T49N286A-dddNLGI	Available now	NET
8752CYLFT	None	8T49N286A-dddNLGI8	Available now	NET
91857AGLF	None	95V857AGLF	Available now	MIP
91857AGLFT	None	95V857AGLFT	Available now	MIP
97U870AKLF	None	None	N/A	MIP
97U870AKLFT	None	None	N/A	MIP
97ULP844AHLF	None	None	N/A	MIP
97ULP844AHLFT	None	None	N/A	MIP
EVC80KSW0005	None	None	N/A	FCM
TSI352-66CQY	None	None	N/A	ACP
TSI564A-10GCL	None	TSI574-10GCLV	Available now	FCM



Integrated Device Technology, Inc.
6024 Silver Creek Valley Road
San Jose, CA 95138

Device to be Discontinued	Drop in Replacement	Functional Replacement	Replacement Part Availability	Product Group
TSI564A-10GCLY	None	TSI574-10GCLV	Available now	FCM
TSI564A-10GIL	None	TSI574-10GILV	Available now	FCM
TSI564A-10GILY	None	TSI574-10GILV	Available now	FCM
TSI572-10GCL	None	TSI577-10GCLV	Available now	FCM
TSI572-10GIL	None	TSI577-10GILV	Available now	FCM
TSI576-10GCLY	None	TSI577-10GCLV	Available now	FCM
TSI576-10GILY	None	TSI577-10GILV	Available now	FCM
TSI620-10GCL	None	None	N/A	FCM
TSI620-10GCLV	None	None	N/A	FCM
TSI620-10GIL	None	None	N/A	FCM
TSI620-10GILV	None	None	N/A	FCM

"ddd" is the dash code number to identify the pre-defined factory programmed configurations. For the specific, publicly available -ddd order codes, refer to FemtoClock NG Universal Frequency Translator Ordering Product Information document. For custom -ddd order codes, please contact IDT for more information.